Kantronics D4-10 Errata Sheet

The following information became available after printing the manual for the D4-10, 70 cm data transceiver. Please make the following corrections to your manual.

On Page 6 (Installation) add the following note to the bottom of the page:

NOTE: Shielded cable must be used for all connections to the Analog port and the TTL port of the D4-10 radio. Failure to use shielded cable may render the Part 15, Sub-Part J FCC certification invalid.

On page 16 (Disassembly Instructions) add the following:

la. Remove the screw located near the center of the front panel.

On page 16 (Assembly Instructions) add the following:

5. Install the screw securing the PC board to the front panel. Failure to install this screw will render the Part 15, Sub-Part J FCC certification invalid.

